

**\*MANDATORY SERVICE BULLETIN\***

**NUMBER:** SB-014 Revision A

**DATE:** 7/17/09

**SUBJECT:** FUEL SYSTEM; DOUBLER RING SCREW INSPECTION

**SUMMARY**

**RECURRENT REQUIREMENTS**

No recurrent requirements associated with this Mandatory Service Bulletin.

**BACKGROUND**

Quest is requiring a one time inspection on the Fuel Doubler Plate (P/N 100-828-4431) to ensure that the correct length of screw (P/N MS24694S52) is installed.

**ACTION**

Extract one of the three screws that hold the Fuel Doubler Plate in place and ensure that it is a MS24694S52. If it is a MS24694S50, replace it with the correct sized screw.

**EFFECTIVITY**

KODIAK 100 Series Aircraft, Serial Numbers 100-0011 through 100-0017.

**AFFECTED PARTS**

KODIAK PART AFFECTED:

- P/N 100-828-4431

REPLACEMENT PART FOR AIRCRAFT RECORDS:

- P/N MS24694S52 x3 (If needed)

**COMPLIANCE**

This Mandatory Service Bulletin must be completed at the earliest convenience, not to exceed the next 100 hour inspection.

**INDUSTRY SUPPORT INFORMATION**

None

**MANPOWER**


This procedure will take approximately 30 minutes to complete and can be completed with one person.

**COMPLETION**

Update the KODIAK Maintenance Log Books.

**WARRANTY INFORMATION**

This modification is warranty reimbursable for the manpower listed above after Quest Aircraft has been notified of your completion.



**Figure 1: MS24694S52 and MS24694S50 screws.**

Quest Aircraft Company, LLC  
© Copyright 2008  
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.

\*MANDATORY SERVICE BULLETIN\*

\*MANDATORY SERVICE BULLETIN\*



**\*IMPORTANT SERVICE BULLETIN\***

Doubler Plate Screw Inspection

## **INSPECTION INSTRUCTIONS**

# Fuel Doubler Plate Screw Inspection


Task

Instruction

1

Do not drain the fuel out of the bay.

Extract one screw from the Fuel Doubler Plate (P/N 100-828-4431).



2



Measure the screw and ensure that it is a **MS24694S52**. If the screw is the correct size, re-install the screw and note the work performed in the KODIAK 100 Log Books.

**NOTE:** There is no need to check the other two screws unless the customer so desires.

If it is a **MS24694S50**, please continue to **Step 3** that will explain the process of how to remove the **MS24694S50** short screws and replace them with the **MS24694S52** which are the correct length screws.



# Fuel Doubler Plate Screw Inspection

Task	Instruction	Instruction
3	<p>Turn the overhead fuel selector valves located in the cockpit to <b>CLOSED</b>.</p> <p>Do not drain the fuel out of the bay.</p> <p>Extract one of the 3 screws as shown.</p>	 <p>Fuel Drain</p> <p>Remove Screw</p>
4	<p>Install the Philips screw (P/N <b>MS24694S52</b>).</p>	 <p>Fuel Drain</p>
5	<p>Repeat the process for the remaining two screws, removing one at a time and installing the correct sized screws. (P/N <b>MS24694S52</b>)</p>	
6	<p>Note the work performed in the KODIAK 100 Log Books.</p>	