

## MANDATORY SERVICE BULLETIN

### REVISION RECORD

REV	DATE	PAGE	CHANGE DESCRIPTION
00	02/29/2024	ALL	Initial release.
01	03/21/2024	1	Update Original Effective Date: WAS 3/1/2024; IS: 4/2/2024

### SUBJECT

Pitch Trim Actuator Maintenance

### EFFECTIVITY

Original Effective Date: 04/02/2024

Serial Range: 100-0001 through 100-0338

### SUMMARY

Daher has developed specific procedures for testing and servicing Kodiak pitch trim actuators. This Service Bulletin is intended to bring these new procedures to the attention of Kodiak 100 owners and mandate an initial compliance. Detailed information can be found in the Field Service Instruction listed below.

DOCUMENT NUMBER	TITLE
FSI-184	Pitch Trim Actuator Maintenance

### COMPLIANCE

This Mandatory Service Bulletin must be complied with at or before the next annual inspection.

SB24-01 has a one time compliance requirement only. Future pitch trim actuator maintenance schedule will be detailed in Chapter 5 of the **AM902.0, Kodiak 100 Airplane Maintenance Manual**, Revision 32 or later.

### CREDIT AND WARRANTY INFORMATION

Daher will reimburse up to eight (8) hours of the labor costs associated with this Service Bulletin for all Kodiak 100 airplanes within the factory airframe warranty. This offer will be valid for one year and one month from release of this bulletin.

**Kodiak Aircraft Company**  
1200 Turbine Drive  
Sandpoint, Idaho 83864

**Kodiak Care**  
Toll Free: 1 (866) 263-1112  
Email: [kodiakcare@daher.com](mailto:kodiakcare@daher.com)