

MANDATORY SERVICE BULLETIN

REVISION RECORD

REV	DATE	PAGE	CHANGE DESCRIPTION
00	11/05/2025	ALL	Initial release
01	12/02/2025	1	Changed Credit and Warranty Information to read “eight (8)” hours to match FSI-194.

SUBJECT

Kodiak 900 Wing Skin and Forward Flap Track Chafe Protection

EFFECTIVITY

Original Effective Date: 11/05/2025

Serial Range: K2-0002 through K2-0020

SUMMARY

Damage may occur to the Wing Skins and Forward Flap Tracks caused by the Flap Track Fairings. The accompanying Field Service Instruction (FSI) gives procedures for evaluating and repairing any damage to the Wing Skins and Forward Flap Tracks, and for preventing future damage by trimming the Flap Track Fairings and installing a rubber gasket.

DOCUMENT NUMBER	TITLE
FSI-194	Forward Flap Track Fairing Chafe Protection

COMPLIANCE

This Mandatory Service Bulletin must be complied with on or before the next annual, 100 hour, or progressive major inspection, whichever comes first.

FAA APPROVAL STATUS

The resultant alteration or repair to the affected airplane described above has been shown to comply with the applicable FAA regulations and is FAA approved.

CREDIT AND WARRANTY INFORMATION

Kodiak Aircraft Company will provide the part needed for this modification (P/N X1010) and reimburse up to eight (8) hours of labor for work performed by a technician who has completed Daher approved Kodiak Maintenance training. This offer will only be valid for 13 months from release of this bulletin.

Contact Kodiak Care to order FSI-194 and the accompanying kit. Refer to Kodiak’s technical publications portal at <https://kodiakcare.aero> for warranty claim reimbursement instructions.

Kodiak Aircraft Company
1200 Turbine Drive
Sandpoint, Idaho 83864

Kodiak Care
Toll Free: 1 (866) 263-1112
Email: care@daher.com