

MANDATORY SERVICE BULLETIN**REVISION RECORD**

REV	DATE	PAGE	CHANGE DESCRIPTION
00	03/27/2026	ALL	Initial release.

SUBJECT

Kodiak Flap Actuators

EFFECTIVITY

Original Effective Date: 03/27/2026

Electromech Flap Actuators (P/N 100-621-0100) within part serial number range 1659 through 1768

The following Kodiak serial numbers were originally certified and delivered with Flap Actuator serial numbers within this affected range:

Kodiak 100 Serial Range: 100-0361 through 100-0364

Kodiak 900 Serial Range: K2-0022 through K2-0029

SUMMARY

Inspect the Flap Actuators to verify the part serial numbers. Flap Actuators within the affected serial number range must be removed and replaced prior to further flight. Airplanes with Flap Actuators within the affected part serial number range are considered not airworthy. Contact Kodiak Care for further assistance.

COMPLIANCE

This Mandatory Service Bulletin must be complied with prior to further flight.

SPECIAL INSTRUCTIONS

There are four (4) Flap Actuators installed on each Kodiak airplane, two (2) in each wing. The Flap Actuator part serial number is listed on a nameplate that is visible when the airplane flaps are in the full down position. See **Figure 1 - Flap Actuators**.


MANDATORY SERVICE BULLETIN

Figure 1: Flap Actuators

CREDIT AND WARRANTY INFORMATION

Kodiak Care will provide replacement units for any affected Flap Actuators that fall within the part serial number range 1659 through 1768. Kodiak Aircraft will reimburse up to 20 hours of labor to perform the Flap Actuator replacements.

Refer to Kodiak's technical publications portal at <https://kodiakcare.aero> for warranty claim reimbursement instructions.

FAA APPROVAL STATUS

The resultant alteration (or repair) to the affected airplane described above has been shown to comply with the applicable FAA regulations and is FAA approved.

Kodiak Aircraft Company
1200 Turbine Drive
Sandpoint, Idaho 83864

Kodiak Care
Toll Free: 1 (866) 263-1112
Email: care@daher.com