DAHER

RECOMMENDED SERVICE BULLETIN

REVISION RECORD

REV	DATE	PAGE	CHANGE DESCRIPTION
00	08/28/2025	ALL	Initial release.

SUBJECT

Kodiak 900 TKS Nuisance Alerts

EFFECTIVITY

Original Effective Date: 08/28/2025

Serial Range: K2-0002 through K2-0016

SUMMARY

Kodiak 900 airplanes with software version 006-B4000-02 installed may experience nuisance TKS flow and pressure indications. Update software in accordance with SN24-01 Revision 02 or later.

DOCUMENT NUMBER	TITLE
SN24-01	Garmin G1000 NXi Software Configurations and Updates for the Kodiak 900

COMPLIANCE

This Recommended Service Bulletin should be complied with at or before the next annual inspection.

FAA APPROVAL STATUS

The resultant alteration (or repair) to the affected airplane described above has been shown to comply with the applicable FAA regulations and is FAA approved.

CREDIT AND WARRANTY INFORMATION

For airplanes with an active Kodiak Airplane Maintenance Program Subscription, Kodiak will reimburse up to three (3) hours of labor to perform this software upgrade.

Claim reimbursement instructions and SN24-01 are available at https://kodiakcare.aero.

Kodiak Aircraft Company
1200 Turbine Drive
Sandpoint, Idaho 83864

Kodiak Care
Toll Free: 1 (866) 263-1112
Email: care@daher.com