

SERVICE NOTICE

SUBJECT

GTX 33ES ADS-B OUT Transponder Upgrade.

EFFECTIVITY

100-0001 and up.

BACKGROUND

This Service Notice is to make customers aware of the option to replace the Garmin GTX 33 Transponder (GTX 33) with the Garmin GTX 33ES ADS-B OUT Transponder (GTX 33ES). The GTX 33ES complies with the ADS-B mandate established by the FAA, which requires aircraft operating in most controlled U.S. airspace to be ADS-B OUT capable by January 1, 2020. Incorporating the GTX 33ES in the KODIAK® 100 also supports ADS-B OUT compliance in many areas of the world.

DISCUSSION

Refer to FSI-136 for detailed information regarding procedures for the removal of the Garmin GTX 33 Transponder (GTX 33), installation of the Garmin GTX 33ES ADS-B OUT Transponder (GTX 33ES), and subsequent Garmin software option loading. After completing FSI-136, ensure that the *AM901.0 KODIAK® 100 Pilot's Operating Handbook and Airplane Flight Manual* (POH) is at Revision 18 or later. Contact Quest Customer Service with questions related to maintenance material.

Table 1–1: REFERENCES

DOCUMENT NUMBER	TITLE
FSI-136	<i>GTX 33ES ADS-B OUT TRANSPONDER UPGRADE</i>
AM901.0	<i>KODIAK® 100 PILOT'S OPERATING HANDBOOK AND AIRPLANE FLIGHT MANUAL</i>

Quest Aircraft Company LLC
1200 Turbine Drive
Sandpoint, Idaho 83864

Quest Customer Service
Phone: (208) 263-1111 **Toll Free:** 1 (866) 263-1112
Email: customerservice@questaircraft.com