

IMPORTANT SERVICE NOTICE

NUMBER: SN-006 (GARMIN Service Advisory No. 0912 Revision A Attached)

DATE: 05/29/2009

SUBJECT: SBAS Operations in Australia, New Zealand and South Pacific Regions

SUMMARY

QUEST AIRCRAFT RECOMMENDS THAT EACH OPERATOR EXAMINE THIS SERVICE NOTICE IMMEDIATELY.

CONCURRENT REQUIREMENTS

None

BACKGROUND

The affected Garmin navigation systems are designed to continuously display an EPU value on the satellite status page. Operating outside of the Multi-functional Satellite Augmentation System (MSAS) service area with limited MSAS coverage can cause elevated EPU values to be displayed if MSAS signals are received. Under these circumstances, EPU values are not used for integrity monitoring and high values will not trigger a loss of integrity (LOI) annunciation.

ACTION

Please read the attached Service Advisory from GARMIN for information.

EFFECTIVITY

This Service Notice affects all Garmin G1000, G900X, 6950, Perspective™, Prodigy™ Integrated Avionics Systems, 400W/500W Series and GNS 480 (CNX80) units with WAAS.

COMPLIANCE

Adhere to the directions specified in the attached GARMIN Service Advisory.

INDUSTRY SUPPORT INFORMATION N/A

MANPOWER

N/A

COMPLETION

N/A

Quest Aircraft Company, LLC
© Copyright 2008
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.





SERVICE ADVISORY

NO.: 0912 Rev A

TO: Owners/Operators of Garmin GPS/WAAS products operating in Australia and

New Zealand

DATE: May 29, 2009

SUBJECT: SBAS Operations in Australia, New Zealand and South Pacific Regions

AFFECTED PRODUCTS

All Garmin G1000, G900X, G950, Perspective[™], Prodigy[™] Integrated Avionics Systems, 400W/500W Series and GNS 480 (CNX80) units with WAAS are affected.

DESCRIPTION

The purpose of this advisory is to explain how large Estimated Position Uncertainty (EPU) values might be displayed by the equipment when there are no associated flags or loss of integrity annunciations displayed.

The affected Garmin navigation systems are designed to continuously display an EPU value on the satellite status page. Operating outside of the Multi-functional Satellite Augmentation System (MSAS) service area with limited MSAS coverage can cause elevated EPU values to be displayed if MSAS signals are received. Under these circumstances, EPU values are not used for integrity monitoring and high values will not trigger a loss of integrity (LOI) annunciation.

PILOT ACTION

The flight crew should consider the LOI indications for system status during flight operations and not the EPU. While the EPU is one figure of merit, the LOI provides status of the navigation solution and is the controlling annunciation for integrity of the flight operation being performed.

For installations with GPS software version 3.0 and earlier, Garmin recommends operating the system with SBAS disabled when outside of an SBAS service area if TAWS is an operational requirement. This will neither enhance nor degrade navigation availability outside of SBAS coverage areas.

For installations with GPS software version 3.1 and later, when operating the system with limited coverage of an SBAS (e.g. WAAS or MSAS) system but outside of the service area, Garmin recommends enabling SBAS and allowing the system to automatically select the mode of operation.

RESOLUTION

Garmin recommends that the system is loaded with the latest GPS engine software that is approved for the installation.

© Copyright 2009 Garmin Ltd. or its subsidiaries All Rights Reserved

Perspective™ is a trademark of Cirrus Design Corporation. Prodigy™ is a trademark of Embraer S.A. Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.