

SERVICE NOTICE

NUMBER: SN-027
REVISION: A
DATE: 03/03/2010

SUBJECT: KODIAK POH/AFM 100-000-901 OBSOLETE

EFFECTIVITY:

KODIAK 100 Series Aircraft equipped with GARMIN GDU Software Version 6.14

SUBJECT:

The **KODIAK POH/AFM 100-000-901** is now obsolete and has been replaced with the **KODIAK POH/AFM 100-000-904**. All information applicable to the GARMIN GDU 6.14 Software has been made into a supplement (**KODIAK POH/AFM Supplement 4, GARMIN G1000 GDU Software Version 6.14**) to accompany the **KODIAK POH/AFM 100-000-904**.

AFFECTED MANUALS AND PUBLICATIONS:

- *KODIAK 100 Series Aircraft Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (POH/AFM 100-000-901); **OBSOLETE***
- *KODIAK 100 Series Aircraft Pilot's Operating Handbook and FAA Approved Airplane Flight Manual (POH/AFM 100-000-904)*
- *KODIAK POH/AFM Supplement 4; GARMIN G1000 GDU Software Version 6.14 (POH/AFM 100-000-904 Supplement 4)*

COMPLIANCE:

- Dispose of the **KODIAK 100 Series POH/AFM 100-000-901** in a way that would prevent further use of the material or duplication of any information.
- Add **KODIAK POH/AFM Supplement 4; GARMIN G1000 GDU Software Version 6.14** to the KODIAK POH/AFM 100-000-904 manual.

SERVICE NOTICE

SERVICE NOTICE

Quest Aircraft Company, LLC
© Copyright 2010
All Rights Reserved

No part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Quest Aircraft Company, LLC.