

## SERVICE NOTICE

### REVISION RECORD

REV	DATE	PAGE	CHANGE DESCRIPTION
00	01/01/2026	ALL	Initial release.

### SUBJECT

Fire Extinguisher Replacements for all Kodiak Airplanes

### EFFECTIVITY

Original Effective Date: 01/01/2026

Serial Range: 100-0001 and later.

Serial Range: K2-0002 and later.

### BACKGROUND

This Service Notice is to make customers aware of FSI-199 for the Kodiak 100 and the Kodiak 900 airplanes that replaces Halon fire extinguishers with Halotron BrX fire extinguishers to meet the regulations in the European Union (EU) that will not allow the deployment of Halon fire extinguishers beginning January 1, 2026.

### DISCUSSION

To comply with the Montreal Protocol (the treaty adopted in 1987 to phase out the production and consumption of ozone-depleting substances/ODS), the EU regulates Halon as an ODS substance by enforcing the regulation (EC) n°1005/2009 for all its member states. Therefore, (EC) n°744/2010 requires that deployment of Halon-based handheld fire extinguishers will be prohibited on board civil aircraft operating within the EU as of January 1, 2026.

The locations of the new fire extinguishers are approved for all Kodiak 100 and Kodiak 900 airplane interiors, including the Summit STC interior.

**Table 1-1: REFERENCES**

DOCUMENT NUMBER	TITLE
FSI-199 REV. 00	Fire Extinguisher Replacement for the Kodiak

---

**Kodiak Aircraft Company**  
1200 Turbine Drive  
Sandpoint, Idaho 83864

**Kodiak Care**  
Toll Free: 1 (866) 263-1112  
Email: [care@daher.com](mailto:care@daher.com)